

Tabulation of Bid #15259
B6[CHILLAR REPAIR]

NAME OF BIDDER	TERMS	AMOUNT	DESCRIPTION
Request #209874			
Item #1 Quantity: 1.00 EA Stock # REPLACEMENT OF ONE SCREW COMPRESSOR FOR CIRCUIT # 1 ON MCGUAY CHILLER MODEL # ALS195A SCREW CHILLER PER PROPOSAL, CHECK GATES AND TOLERANCE ON #2 COMPRESSOR.			
MCQUAY CO (GRAND PRAIRIE, TX)	0.0%, 0 NET 30	*19,051.00 EA	
Request #209874			
Item #2 Quantity: 1.00 EA Stock # REPLACENET OF ONE SCREW COMPRESSOR FOR CIRCUIT # 2 ON MCGUAY CHILLER MODEL ALS195A SCREW CHILLER PER PROPOSAL. (THIS COMPRESSOR WILL BE WARRANTED, REBUILD LIQUID LINE SOLENOID FURNISH AND REPLACE CONTACT ON COMPRSSOR STARTER.			
FURNISH AND INSTALL ALL LABOR TOOLS SUPPLIES NECESSARY TO COMPLETE REPLACEMENT OF SCREWW COMPRESSOR. PER ATTACHED SPECIFICATIONS. PROOF OF WORKMEN'S COMPENSATION AND GENERAL LIABILITY MUST ACCOMPANY YOUR AT BID OPENING.			
..... NOTE THE ATTACHED SPECIFICATIONS AND MWBE DOCUMENTATION ARE HEREBY MADE PART OF THIS BID, ALL PRICING MUST INCLUDE TOTAL SCOPE OF WORK TO BE PERFORMED AT INDIVIDUAL SITES. JOHN F. KENNEDY SCHOOL . FOR INFORMATION CONCERNING THIS QUOTE CONTACT 972-925 5200- WAYNE ALLEN[HVAC] NOTE L PLEASE COMPLETE MWBE INFORMATION			
MCQUAY CO (GRAND PRAIRIE, TX)	0.0%, 0 NET 30	*8,866.00 EA	

Tabulation of Bid # 15259
B6[CHILLAR REPAIR]

NAME OF BIDDER	TERMS	AMOUNT	DESCRIPTION

Bid/Quote Summary			
Total number of bids requested:		10	
Total number of compliant bids received:		1	
Total number of HISPANIC MAL bids requested:		4	
Total number of HISPANIC MAL bids received:		0	
Total number of all minority bids requested:		4	
Total number of all minority bids received:		0	

